

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401337015  
Date Received:  
07/11/2017

FIR RESOLUTION FORM

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96705  
Name of Operator: WPX ENERGY PRODUCTION LLC  
Address: P O BOX 3102 MS-25-2  
City: TULSA State: OK Zip: 74101

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
Lacey Granillo	505-333-1816	lacey.granillo@wpxenergy.com
Darren Rowley	505-947-4974	darren.rowley@wpxenergy.com
Deborah Watson	505-333-1880	deborah.watson@wpxenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 685303337  
Inspection Date: 06/14/2017 FIR Submit Date: 06/17/2017 FIR Status:

Inspected Operator Information:

Company Name: WPX ENERGY PRODUCTION LLC Company Number: 96705  
Address: P O BOX 3102 MS-25-2  
City: TULSA State: OK Zip: 74101

LOCATION - Location ID: 333532

Location Name: R&G Number: 26-3 County: LA PLATA  
Qtrqtr: NWSE Sec: 26 Twp: 33N Range: 7W Meridian: N  
Latitude: 37.072410 Longitude: -107.573880

FACILITY - API Number: 05-067-00 Facility ID: 213993

Facility Name: TIFFANY Number: 1  
Qtrqtr: NWSE Sec: 26 Twp: 33N Range: 7W Meridian: N  
Latitude: 37.072410 Longitude: -107.573880

CORRECTIVE ACTIONS:

1  CA# 82370

Corrective Action: Remove debris to comply with Rule 603.f using Rule 603.f guidance document for further details.

Date: 07/12/2017

Response: CA COMPLETED

Date of Completion: 07/07/2017

Operator Comment: Dried weed debris trapped in fencing and corner of location behind produced water tank was removed to comply with Rule 603.f. See attached photograph.

COGCC Decision: Approved via an AMI

COGCC Representative: Approved using operator submitted photo documentation.

2  CA# 82371

Corrective Action: Clean up and remediate stained soil and gravel to comply with Rule 906.a.

Date: 07/12/2017

Response: CA COMPLETED

Date of Completion: 07/07/2017

Operator Comment: Stained soils and gravel were cleaned up and remediated per Rule 906.a. See attached photographs.

COGCC Decision: Approved via an AMI

COGCC Representative: Approved using operator submitted photo documentation.

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Deborah Watson

Signed: \_\_\_\_\_

Title: Environmental Specialist

Date: 7/11/2017 10:37:22 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401337015	FIR RESOLUTION SUBMITTED
401337056	Fence after debris removed
401337062	Produced water tank
401337064	Muffler
401337068	separator
401337075	wellhead 1
401337080	wellhead 2

Total Attach: 7 Files