



Photo 1: View of the project area from the southeastern corner facing center.



Photo 2: View of the eastern portion of the project area from the southeastern corner of the project area facing northward. Revegetation is progressing with grasses such as James galleta (*Pleuraphis jamesii*) and western wheatgrass (*Pascopyrum smithii*).



Photo 3: View of the southern portion of the project area from the southeastern corner facing westward.



Photo 4: View of sediment traps in the southwestern corner of the project area that appear to be functioning.



Photo 5: View of the northern portion of the project area from the northwestern corner facing eastward. Approximately 25 musk thistles should be controlled to prevent infestation during the following growing season.