

# Inspection Photos

7/31/2017

Operator: REX ENERGY ROCKIES LLC - 10336

Location ID: 420938

Inspection Doc. Number: 675103775

Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: REX ENERGY ROCKIES LLC - 10336  
Location ID: 420938



**Photo 1:** Photo taken from the location, facing north. Photo shows starting point for the disturbance transect. Photo shows vegetation over the reclamation area.



**Photo 2:** Photo taken from the location, facing west. Photo shows the 50<sup>th</sup> point for the disturbance transect. Photo shows vegetation over the reclamation area.



Inspection Photos  
Operator: REX ENERGY ROCKIES LLC - 10336  
Location ID: 420938



**Photo 3:** Photo taken from the location, facing east. Photo shows the 50<sup>th</sup> point for the disturbance transect. Photo shows vegetation over the reclamation area.



**Photo 4:** Photo taken from the location. Photo shows the 50<sup>th</sup> point for the disturbance transect. Photo shows vegetation over the reclamation area.



Inspection Photos  
Operator: REX ENERGY ROCKIES LLC - 10336  
Location ID: 420938



**Photo 5:** Photo taken from the location, facing south. Photo shows the end point for the disturbance transect. Photo shows vegetation over the reclamation area.



**Photo 6:** Photo taken from the reference, facing north. Photo shows starting point for the reference transect. Photo shows vegetation over the reference area.

Inspection Photos  
Operator: REX ENERGY ROCKIES LLC - 10336  
Location ID: 420938



**Photo 7:** Photo taken from the reference, facing west. Photo shows the 50<sup>th</sup> point for the reference transect. Photo shows vegetation over the reference area.



**Photo 8:** Photo taken from the reference, facing east. Photo shows the 50<sup>th</sup> point for the reference transect. Photo shows vegetation over the reference area.





**Photo 9:** Photo taken from the reference,. Photo shows the 50<sup>th</sup> point for the reference transect. Photo shows vegetation over the reference area.



**Photo 4:** Photo taken from the reference, facing south. Photo shows end point for the reference transect. Photo shows vegetation over the reference area.