

# Inspection Photos

7/31/2017

Operator: NOBLE ENERGY INC - 100322

Location ID: 326968

Inspection Doc. Number: 675103782

Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 326968



**Photo 1:** Photo taken from the south end of the location, facing northwest. Photo shows the location.



**Photo 2:** Photo taken from the south end of the location, facing northeast. Photo shows the location.

Inspection Photos  
Operator: NOBLE ENERGY INC - 100322  
Location ID: 326968



**Photo 3:** Photo taken from the location. Photo shows pipe riser equipment remains on the location.



**Photo 4:** Photo taken from the northeast end of the location, facing north. Photo shows areas of the location that have not been re-contoured and reclaimed.



**Photo 5:** Photo taken from the northeast corner of the pit location, facing west. Areas where the pit wall had existed remains unvegetated. Areas may require additional remediation.



**Photo 6:** Photo taken from the northeast corner of the pit location, facing west. Areas where the pit wall had existed remains unvegetated. Areas may require additional remediation.



**Photo 7:** Photo taken from the access road, facing north. Gravel remains evident at access road, and road remains predominantly unvegetated and does not meet reclamation requirements.