

**Inspection Photos**  
**Location Name: Simpson #1**  
**API: 05-123-11328**



**1) Wellhead looking north, no sign posted**



**2) Wellhead looking southeast**

**Inspection Photos**  
**Location Name: Simpson #1**  
**API: 05-123-11328**



**3) Wellhead looking south**



**4) Tank battery looking west, no contents or capacity posted**



**Inspection Photos**  
**Location Name: Simpson #1**  
**API: 05-123-11328**



**5) Tank battery looking west**



**6) Water vault looking west. No contents, capacity, or NFPA label**



**Inspection Photos**  
**Location Name: Simpson #1**  
**API: 05-123-11328**



**7) North side of tank battery animal burrow**



**8) West side of tank battery looking east at animal burrow**

**Inspection Photos**  
**Location Name: Simpson #1**  
**API: 05-123-11328**



**9) Picture of battery from south east**



**10) Crude tank from south, no contents or capacity posted**