

Inspection Photos
Location Name: Po 12-12
API: 05-081-06904



Photo 1. Overview of location from entrance facing west.

Inspection Photos
Location Name: Po 12-12
API: 05-081-06904



Photo 2. Weeds on location.



Photo 3. Overgrown road. Taken at entrance to location facing off location.