

Inspection Photos
Location Name: Latin 33-12
API: 05-081-06898



Photo 1. Overview of location from entrance facing northeast.

Inspection Photos
Location Name: Latin 33-12
API: 05-081-06898



Photo 2. Produced water tank marked out of service stored on location.



Photo 3. Seperator treater marked out of service stored on location.