

Inspection Photos  
Location Name: McCallum Unit 97  
API: 05-057-06162



Photo 1. Overview of location taken at entrance facing south.



Photo 2. Stained soil at wellhead.