

Inspection Photos
Location Name: Hi-Land 10G
API: 05-001-08768



Wellhead (10G on left 10B on right)



Pumping unit frame, **Corrective action: Trash at unit.**

Inspection Photos
Location Name: Hi-Land 10G
API: 05-001-08768



Wellhead signage, from 6/20/2017 inspection photos.
Corrective action: No emergency contact info.



Wellhead signage, **Corrective action: No emergency contact info added.**

Inspection Photos
Location Name: Hi-Land 10G
API: 05-001-08768



Wellhead, from 6/20/2017 inspection photos. Corrective action: Stained soil at wellhead



Wellhead, Corrective action: Stained soil not remediated.

Inspection Photos
Location Name: Hi-Land 10G
API: 05-001-08768



Battery View



Separator housing