



**photo 1:** Facing south toward the location.



**photo 2:** South side of the location facing north.





**photo 3:** There is tall undesirable weed growth throughout the location (Russian thistle, Kochia sp.).



**photo 4:** View of vegetation cover at the location. There is new germination of grasses beginning to establish. Some of the new germination also appears to be dying off.





**photo 5:** Facing north toward the surrounding undisturbed pasture.