

Cover Data

Date: 7/28/2017 Inspected By: Ryan Costa
 Location/Operator: Running Foxes Petroleum API # 073-06349

Transect #/disturbed/Ref	Disturbed		Reference					
Transect Orientation and first photo, degrees	38.94004 -103.61043	S	38.94358 -103.61142	SW				
Photo Midpoint (2)	W, E		NW, SE					
End transect	38.93977 -103.61037	N	38.94334 -103.61162	NE				
Photo other								
Aspect/Slope	S/10%		Flat					
		Totals		Totals		Totals		Totals
Cryptogams (eg. Moss, lichen)								
Litter				29				
Bare Soil				20				
Rock								
Total Weeds	38							
Total Desirable Species	9		51					
80% Check	9/51 = 17.6%							
	1st Hit	2nd/P	1st Hit	2nd/P	1st Hit	2nd/P	1st Hit	2nd/P
Sal sp. Russian thistle	2	26						
Kochia sp.	1	9						
Amb. sp. Ragweed	1	3						
Gas smi	1	2		P				
Bro ine	1	7						
Chr vil				5				
Ari pur				3				
Bou gra				20				
Art fil				2				
Spo cry				10				
Isa ten				2				
Yuc gla				1				
Val oct				2				
Muh tor				6				
Fla rat				1				
Cr och				1				
Opn pol				1				

2nd= second hit; P= plant species present but not hit




photo 1: Facing south at the beginning of vegetation transect at the location (Disturbed).



photo 2: Groundcover at the midpoint of vegetation transect at the location (Disturbed).



photo 3: Facing north at the end of vegetation transect at the location (Disturbed).




photo 4: Facing southwest at the beginning of vegetation transect off location (reference).



photo 5: Groundcover at the midpoint of vegetation transect off location (reference).



photo 6: Facing northeast at the end of vegetation transect off location (reference).