

Interim Reclamation Inspection

August 1, 2017

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 327882

Weld County, CO

NESW Section 36 T4N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HSR-CONLEY #11-36A
Location ID: 327882



Google Earth aerial imagery taken September 7, 2016 illustrating the subject well pad for this follow-up interim reclamation inspection (outlined in the green dashed line).

Inspection Photos
Location Name: HSR-CONLEY #11-36A
Location ID: 327882



Photo 1. Photo taken from the southeast well pad, facing South. Desirable plant species establishment is evident throughout this area but not as uniform as other interim areas.



Photo 2. Photo taken from the southeast well pad, facing South. Desirable plant species establishment is evident throughout this area but not as uniform as other interim areas.

Inspection Photos
Location Name: HSR-CONLEY #11-36A
Location ID: 327882



Photo 3. Photo taken from the central interim area, facing Northwest. Desirable plant species establishment is evident throughout this area but not as uniform as other interim areas.



Photo 4. Photo taken from the central interim area, facing Southwest. Desirable plant species establishment is evident throughout this area.

Inspection Photos
Location Name: HSR-CONLEY #11-36A
Location ID: 327882



Photo 5. Photo taken from the west central interim area, facing South. Desirable plant species establishment is evident throughout this area.



Photo 6. Photo taken from the west central interim area, facing North. Desirable plant species establishment is evident throughout this area.