

# Final Reclamation Inspection

August 3, 2017

Operator: WELLINGTON OPERATING COMPANY - 95233

API: 05-069-05284

Larimer County, CO

NESW Section 7 T9N R68W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: WELLINGTON MUDDY UNIT #25-1  
API: 05-069-05284



**Photo 1.** Photo taken from the well location, facing North. Location does not meet Rule 1004 standards. Gravel pile and gravel remains at the well location, and noxious weeds were observed. Well marker does not comply with Rule 319.a.(5).

**Photo 2.** Photo taken north of the gravel pile, facing South. Pipe risers remain at location. See following photos.

Inspection Photos

Location Name: WELLINGTON MUDDY UNIT #25-1

API: 05-069-05284



**Photo 3.** Close-up photo (1 of 2) taken of some of the pipe risers at location.



**Photo 4.** Close-up photo (2 of 2) taken of some of the pipe risers at location.

Inspection Photos

Location Name: WELLINGTON MUDDY UNIT #25-1

API: 05-069-05284



**Photo 5.** Photo taken from the well location, facing West. Location does not meet Rule 1004 standards.



**Photo 6.** Reference photo taken west of location, facing North. Well location is not reflective of reference area vegetative levels.