



Photo 1: View of the project area from the northeastern corner facing center.



Photo 2: View of the northern portion of the project area from the northeastern corner of the well pad facing westward. Revegetation is progressing with grasses such as western wheatgrass (*Pascopyrum smithii*) and James galleta (*Pleuraphis jamesii*).



Photo 3: View of the eastern portion of the project area from the northeastern corner of the well pad facing southward.



Photo 4: View of sediment trap near the well pad entrance that appears to be functioning.