



**Photo 1: View of the project area from the northwestern corner facing center.**



**Photo 2: View of the western portion of the project area from the northwestern corner of the well pad facing southward. Revegetation is progressing with grasses and shrubs such as western wheatgrass (*Pascopyrum smithii*) and rubber rabbitbrush (*Chrysothamnus nauseosus*).**



**Photo 3: View of the northern portion of the project area from the northwestern corner of the well pad facing eastward. Silt traps appear to be functioning.**