

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/08/2017

Submitted Date:

08/04/2017

Document Number:

679100101

FIELD INSPECTION FORM

Loc ID 316193 Inspector Name: KUBECZKO, DAVE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10539
Name of Operator: SWEVCO - SABW LLC
Address: 1125 ESCALANTE DR
City: RANGELY State: CO Zip: 81648

Findings:

- 1 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Steven Hale		shale@utahgascorp.com	
Dave Kubeczko		dave.kubeczko@state.co.us	

General Comment:

Date of Inspection: 06-08-17
Type of Inspection: Containment, Stormwater
Location Name: PMF-62S103W /31SWSW Pad; Park Mountain Federal #9029, 1-31-2-103 Well;
Location ID #: 316193
API #: 05-103-09977
Observed site reclamation and stormwater/erosion control on 06-08-17 (no previous COGCC inspection conducted at this location); no surface indication of pit; site is partially reclaimed with natural vegetation; no evidence of leaks or spills at wellhead; tank has secondary containment - no evidence of leaks or spills; stormwater/erosion controls are adequate - no indication of offsite migration of fluids or sediment from well pad; signage was still previous operator.