

Inspection Photos
Location Name: Wyatt 33-22
API: 05-123-16089



Photo 1. Well sign operator name unreadable as previous operator name bleeding through

Photo 2. Wellhead looking north Note well in alleyway

Inspection Photos
Location Name: Wyatt 33-22
API: 05-123-16089



Photo 3. Unknown debris on west side of wellhead



Photo 2. Well looking south

