

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/01/2017

Submitted Date:

08/01/2017

Document Number:

679902811

FIELD INSPECTION FORM

Loc ID 324880 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10324
Name of Operator: NEWELL ENERGY LTD
Address: PO BOX 830808
City: SAN ANTONIO State: TX Zip: 78283

Findings:

- 6 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------------|--------------|--------------|---------|
| Trbovich, Laurence | 719-388-1839 | trbo@nrsa.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 213380 | WELL | PR | 07/01/2005 | GW | 061-06742 | ARWOOD 1 | PR |

General Comment:

Location

| | | | |
|--------------------|---------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Dirt road through pasture | | |
| Corrective Action: | | Date: | |

Overall Good:

| | | | |
|----------------------|----------------------------------------------------------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Lease sign mounted to fence by unit | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Sticker on HHS and 210bbl tank. ADD COMPLETE LABELING TO 300BBL TANK | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

Multiple Spills and Releases?

| | | | |
|--------------------|------------------------------------------------------------------------------|-------|--|
| Fencing/: | | | |
| Type | LOCATION | | |
| Comment: | Wire fence and metal panels around unit, wellhead, tanks, metal shed and HHS | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|----|-------|--|
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|--|-------|--|
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 213380 Type: WELL API Number: 061-06742 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |

Comment: [Erosion from recent rainfall will need maintenance](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT