

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/01/2017

Submitted Date:

08/01/2017

Document Number:

679902816

FIELD INSPECTION FORM

Loc ID 324886 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 81480
Name of Operator: THOMAS L SPRING LLC
Address: 7400 E ORCHARD RD STE 106-S
City: GREENWOOD State: CO Zip: 80111

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Springs, Tom	303-771-1889 off/68710	T1spring@aol.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256446	WELL	PR	03/12/2003	GW	061-06759	CASTLEWOOD 1-8	PR

General Comment:

(This area is currently blank for general comments.)

Location			
Lease Road:			
Type	Access		
comment:	Dirt road through pasture		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign mounted to meter shed		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Metal sign by water tank		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:	Pipe fence around water tank		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Pipe fence around wellhead		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Pipe fence around HGS and meter shed		
Corrective Action:			Date:
Equipment:			
Type: Horizontal Heated Separator	# 1		corrective date
Comment:	HGS next to meter shed		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	Open Top		38.337600,-102.819140
Comment: 40bbls Fiberglass open top water tank w/Adequate wildlife netting					
Corrective Action:					Date:
Paint					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 256446 Type: WELL API Number: 061-06759 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: [Access has deep tracks and needs maintenance. Erosion on west side of location needs maintenance.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT