

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/01/2017

Submitted Date:

08/01/2017

Document Number:

679902817**FIELD INSPECTION FORM**

Loc ID 324784 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10017Name of Operator: CHACO ENERGY COMPANYAddress: P O BOX 1587City: DENVER State: CO Zip: 80201**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Nelson, Alan	(405)942-3751	chaco@swbell.net	Production Manager

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212570	WELL	PR	02/01/2011	GW	061-05020	F L PYLES 1	PR

General Comment:

Location

Lease Road:			
Type	Access		
comment:	Dirt road through CRP		
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Stickers and stencils on tanks		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lease sign mounted to fence at tank battery		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Wire fence around tank battery		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Metal panels around HGS		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Metal panels around wellhead		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Pipe fence around meter shed		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:	HGS on south side of meter shed		
Corrective Action:		Date:	

Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	<100 BBLs	STEEL AST		38.315590,-102.810800
Comment:	2-90bbls Steel production tanks				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Berms need maintenance			
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	212570	Type:	WELL	API Number:	061-05020	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			
Compaction	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT