



Photo 1: View of the project area from the northwestern corner facing center.



Photo 2: View of the western portion of the project area from the northwestern corner of the well pad facing southward. Portion of the revegetation in the interim reclamation area is progressing with grasses such as western wheatgrass (*Pascopyrum smithii*). Other portions are weedy with concentrations of cheatgrass (*Bromus tectorum*).



Photo 3: View of musk thistles within the eastern portion of the project area.



Photo 4: View of sediment deposition and stormwater flow pattern in the southeastern portion of the project area.



Photo 5: View of more sediment deposition downstream of Photo 4, where it appears sediment is being carried offsite into adjacent sagebrush shrubland.



Photo 6: View of rilling and scouring from stormwater flows exiting the eastern portion of the project area.