

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/28/2017

Submitted Date:

08/04/2017

Document Number:

679100104**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: KUBECZKO, DAVE On-Site Inspection ☒ 2A Doc Num: 401252504

Operator Information:OGCC Operator Number: 96735Name of Operator: WILLIFORD RESOURCES, L.L.C.Address: 6506 S LEWIS AVE STE 102City: TULSA State: OK Zip: 74136**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Dave Kubeczko		dave.kubeczko@state.co.us	
Linda Callahan		lcallahan@swbell.net	

General Comment:

Date of Inspection: 06-28-17

Type of Inspection: Form 2A Pre-Permit Approval Onsite

Location Name: West Combustor Facility

Form 2A # 401252504

Location ID #: NA

API #: NA

Conducted onsite for proposed combustor pad location (approximately 30' by 30') with operator on 06-28-17; location will have a gravel pad, combustor, liquids knock-out tank, and flowlines; location is near existing gathering line so minimal disturbance for hookup will be needed; location is dry pasture and will not require interim reclamation since the combustor will operate for the lifetime of the oil and gas wells in this field; location should be inspected once constructed, flowline tested, and in operation.