

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/31/2017

Submitted Date:

08/03/2017

Document Number:

673715870**FIELD INSPECTION FORM**

Loc ID 322165 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 74165Name of Operator: RENEGADE OIL & GAS COMPANY LLCAddress: 6155 S MAIN STREET #210City: AURORA State: CO Zip: 80016**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name   | Phone          | Email                    | Comment                         |
|----------------|----------------|--------------------------|---------------------------------|
| Ingve, Ed      | (303) 680-4725 | ed@renegadeoilandgas.com | <a href="#">All Inspections</a> |
| Condill, J.B.  | (303) 680-4725 | jbcrog@aol.com           | <a href="#">All Inspections</a> |
| Espinosa, Bill | (303) 829-4982 | billespinosa30@yahoo.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name        | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 209449      | WELL | PR     | 07/28/2004  | OW         | 039-06354 | CHAMPLIN 569 AMOCO 1 | PR          |

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

Emergency Contact Number:

|                    |              |             |
|--------------------|--------------|-------------|
| Comment:           | 303-680-4725 |             |
| Corrective Action: |              | Date: _____ |

Overall Good: ☐**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?**Fencing/:**

|                    |             |       |  |
|--------------------|-------------|-------|--|
| Type               | WELLHEAD    |       |  |
| Comment:           | barbed wire |       |  |
| Corrective Action: |             | Date: |  |

**Equipment:**

|                          |                                |       |                 |
|--------------------------|--------------------------------|-------|-----------------|
|                          |                                |       | corrective date |
| Type: Prime Mover        | # 1                            |       |                 |
| Comment:                 | electric motor, electric panel |       |                 |
| Corrective Action:       |                                | Date: |                 |
| Type: Pump Jack          | # 1                            |       |                 |
| Comment:                 |                                |       |                 |
| Corrective Action:       |                                | Date: |                 |
| Type: Deadman # & Marked | # 4                            |       |                 |
| Comment:                 |                                |       |                 |
| Corrective Action:       |                                | Date: |                 |

**Tanks and Berms:**

|                    |   |          |                     |         |        |       |
|--------------------|---|----------|---------------------|---------|--------|-------|
| Contents           | # | Capacity | Type                | Tank ID | SE GPS |       |
|                    |   |          | CENTRALIZED BATTERY |         | ,      |       |
| Comment:           |   |          |                     |         |        |       |
| Corrective Action: |   |          |                     |         |        | Date: |

**Paint**

|                  |  |  |
|------------------|--|--|
| Condition        |  |  |
| Other (Content)  |  |  |
| Other (Capacity) |  |  |
| Other (Type)     |  |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
|                    |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |  |  |       |
|--------------------|--|--|-------|
| Yes/No             |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

### Location Construction

Location ID: 209449 CDP: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

#### Form 2A COAs:

**Comment:** No COAs.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

#### Wildlife BMPs:

**Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Corrective Action:** \_\_\_\_\_

Date: \_\_\_\_\_

#### On Site Inspection (305):

##### Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

##### Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

##### LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

##### Summary of Landowner Issues:

\_\_\_\_\_

##### Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

##### Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

| Inspected Facilities |  |       |      |             |           |         |    |               |    |
|----------------------|--|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 209449                                   | Type: | WELL | API Number: | 039-06354 | Status: | PR | Insp. Status: | PR |
| Producing Well       |  |       |      |             |           |         |    |               |    |
| Comment:             | PR. May 2017 reported to COGCC database. |       |      |             |           |         |    |               |    |
| Corrective Action:   |  |       |      | Date:       |           |         |    |               |    |

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: pasture**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

- 1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_
- 1003c. Compacted areas have been cross ripped? \_\_\_\_\_
- 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_
- Cuttings management: \_\_\_\_\_
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_
- Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

**Overall Interim Reclamation****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |               |                          |         |
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                   | URL   |
|--------------|-------------------------------|---|
| 673715918    | Renegade Champlin 569 Amoco 1 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4218212">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4218212</a> |