

- State CD 1 05-067-07752



Photo 1: Wellhead sign.

- State CD 1 05-067-07752



Photo 2: Produced water tank sign.

- State CD 1 05-067-07752



**Photo 3: Canada Thistle growing on perimeter.**

- State CD 1 05-067-07752



**Photo 4: Failed check dam and Canada Thistle.**

- State CD 1 05-067-07752



**Photo 5: Failed rip rap.**

- State CD 1 05-067-07752



**Photo 6: Un-staked waddle.**

- State CD 1 05-067-07752



**Photo 7: Excavated 1" riser.**

- State CD 1 05-067-07752



**Photo 8: Excavated 1" line at separator. Valve inside cabinet is locked out and painted.**

- State CD 1 05-067-07752



**Photo 9: Impacted soil and gravel.**

- State CD 1 05-067-07752



**Photo 10: Sediment deposits inside fenced production equipment area.**