

August 3, 2017 COGCC Environmental inspection of Grynberg's Chivington #1 Location (Location ID: 321854.



Secured Location and gate. Note: debris in fence.



Looking east down lease road.



Looking west across Location.



Looking west across Location.



Looking west across Location.



View NE corner of Location.



Location.

View north to northeast. Note sediment off of



Location.

View north to northeast. Note sediment off of



Stock pond north of Location.





View looking south along west side of Location.



View looking east along south side of Location. Note, debris coming on Location.



Surface erosion across Location.



Surface erosion across Location.



Surface erosion across Location.



Sediment leaving Location.