

# Final Reclamation Inspection

August 4, 2017

Operator: CDM OIL & GAS - 14740

API: 05-013-06151

Boulder County, CO

NWSE Section 34 T1N R69W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: NUOCI #1  
API: 05-013-06151



**Photo 1.** Photo taken from the approximate center of the well location, facing North. Location appears to be sufficiently stabilized with vegetation and straw mulch until the location is further developed into housing development. Silt fence BMP has been installed along the down gradient southern location as well.



**Photo 2.** Photo taken from the approximate center of the well location, facing East. Location appears to be sufficiently stabilized with vegetation and straw mulch until the location is further developed into housing development. Silt fence BMP has been installed along the down gradient southern location as well.

Inspection Photos  
Location Name: NUOCI #1  
API: 05-013-06151



**Photo 3.** Photo taken from the southern location, facing Southwest. Location appears to be sufficiently stabilized with vegetation and straw mulch until the location is further developed into housing development. Silt fence BMP has been installed along the down gradient southern location as well.



**Photo 4.** Photo taken from the southern location, facing Southwest. Location appears to be sufficiently stabilized with vegetation and straw mulch until the location is further developed into housing development. Silt fence BMP has been installed along the down gradient southern location as well. Silt fence is in need of repair/maintenance along portions of the BMP.



Inspection Photos  
Location Name: NUOCI #1  
API: 05-013-06151



**Photo 5.** Photo taken from the temporary well marker. Operator has communicated and coordinated with the housing developer that this is just a temporary well marker.