

Final Reclamation Inspection

August 4, 2017

Operator: CDM OIL & GAS - 14740

API: 05-013-06166

Boulder County, CO

NESE Section 34 T1N R69W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: NUOCI #2
API: 05-013-06166



Photo 1. Photo taken from the approximate center of the well location, facing East. Location appears to be sufficiently stabilized with vegetation and straw mulch until the location is further developed into housing development. Silt fence BMP has been installed along the down gradient eastern and southern location as well.



Photo 2. Photo taken from the approximate center of the well location, facing North. Location appears to be sufficiently stabilized with vegetation and straw mulch until the location is further developed into housing development. Silt fence BMP has been installed along the down gradient eastern and southern location as well.

Inspection Photos
Location Name: NUOCI #2
API: 05-013-06166



Photo 3. Photo taken from the southern location, facing West. Location appears to be sufficiently stabilized with vegetation and straw mulch until the location is further developed into housing development. Silt fence BMP has been installed along the down gradient eastern and southern location as well.



Photo 4. Photo taken from the temporary well marker. Operator has communicated and coordinated with the housing developer that this is just a temporary well marker. Well marker was not easily visible.