



Photo 1: View of the project area from the northeastern corner facing center.



Photo 2: View of the eastern portion of the project area from the northeastern corner of the well pad facing southward. Revegetation is progressing with grasses such as smooth brome (*Bromus inermis*), meadow barley (*Hordeum brachyantherum*), as well as shrubs such as rubber rabbitbrush (*Chrysothamnus nauseosus*).



Photo 3: View of the northern portion of the project area from the northwestern corner facing eastward.



Photo 4: View of the eastern portion of the project area from the southeastern corner facing northward.