



Photo 1: View of the project area from the northwestern corner facing center.



Photo 2: View of the northern portion of the project area from the northwestern corner of the well pad facing eastward. Revegetation is progressing with grasses such as crested wheatgrass (*Agropyron cristatum*) and western wheatgrass (*Pascopyrum smithii*).



Photo 3: View of the western portion of the project area from the northwestern corner of the well pad facing southward.



Photo 4: View of oil stained soils and pipe riser west of well head on well pad.