

**Inspection Photos**  
**Location Name: Lind 24-1**  
**API: 05-123-18924**



**Pump jack looking south, open top container containing fluid with no wildlife protection**



**Stained soil in pump jack motor shed**

**Inspection Photos**  
**Location Name: Lind 24-1**  
**API: 05-123-18924**



**Stained soil in pump jack motor shed**



**Stained soil in pump jack motor shed**



**Inspection Photos**  
**Location Name: Lind 24-1**  
**API: 05-123-18924**



**Open top container for pump jack blowdown, contains lube oil, has a dead bird in it, no wildlife protection**



**Another picture of the open top container on south side of pump jack motor shed**



**Inspection Photos**  
**Location Name: Lind 24-1**  
**API: 05-123-18924**



**Open top container north side of wellhead containing fluid with no wildlife protection**



**Leaking gear box on east side of pump jack**

**Inspection Photos**  
**Location Name: Lind 24-1**  
**API: 05-123-18924**



**Picture of battery looking north**



**Leaking valves and stained soil inside of separator dog house**



**Inspection Photos**  
**Location Name: Lind 24-1**  
**API: 05-123-18924**



**Unlabeled container on south side of separator**



**2" Unused/unmarked riser on south side of separator**

**Inspection Photos**  
**Location Name: Lind 24-1**  
**API: 05-123-18924**



**Stained soil at East crude tank valve**



**Stained soil at West crude tank valve**



**Inspection Photos**  
**Location Name: Lind 24-1**  
**API: 05-123-18924**



**Tank battery sign looking west**



**Actively growing weeds inside of tank battery looking east**



**Inspection Photos**  
**Location Name: Lind 24-1**  
**API: 05-123-18924**



**Animal burrow inside of berm on west side of tank battery**



**Backside valve of west crude tank, stained soil**

**Inspection Photos**  
**Location Name: Lind 24-1**  
**API: 05-123-18924**



**Tanks looking north, no contents or capacity marked**



**Open plumbing on top of all 3 tanks**