

# Inspection Photos

8/7/2017

Operator: MARKUS PRODUCTION, INC - 53790

Location ID: 406198

Inspection Doc. Number: 675103789

Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC

Inspection Photos  
Operator: MARKUS PRODUCTION, INC - 53790  
Location ID: 406198



**Photo 1:** Photo taken from the battery location, facing east. Photo shows unvegetated areas appear to have been reseeded, and crimped with straw for site stabilization.



**Photo 2:** Photo taken from the battery location, facing east. Photo shows unvegetated areas appear to have been reseeded, and crimped with straw for site stabilization.