

Inspection Photos

8/7/2017

Operator: VAUGHEY & VAUGHEY - 92950

Location ID: 405138

Inspection Doc. Number: 675103798

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the north end of the location. Photo shows reclamation in process.



Photo 2: Photo taken from the reclamation area on the north end of the location. Photo shows germination evident.



Photo 4: Photo taken from the well location. Photo shows reclamation in process.



Photo 5: Photo taken from the reclamation area at the well. Photo shows germination evident.