

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/08/2017

Submitted Date:

08/08/2017

Document Number:

666803474**FIELD INSPECTION FORM**

Loc ID 334911	Inspector Name: Murray, Richard	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>100185</u> Name of Operator: <u>ENCANA OIL & GAS (USA) INC</u> Address: <u>370 17TH ST STE 1700</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202-</u>				Findings: <u>13</u> Number of Comments <u>1</u> Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
Kellerby, Shaun		Shaun.Kellerby@state.co.us	NW Field Supervisor
Contact, General		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267971	WELL	PR	05/28/2004	GW	045-09227	HMU 3-9 (I3B)	PR
267979	WELL	PR	02/19/2004	GW	045-09234	HMU 3-16A (I3B)	PR
267980	WELL	PR	02/19/2004	GW	045-09235	HMU 2-13 (I3B)	PR
267983	WELL	PR	04/30/2004	GW	045-09237	HMU 2-12 (I3B)	PR
273281	WELL	PR	10/07/2005	GW	045-10228	HMU 3-7C (I3B)	PR
273282	WELL	PR	10/08/2005	GW	045-10230	GMU 34-16 (I3B)	PR
273284	WELL	PR	09/27/2005	GW	045-10234	HMU 3-7D (I3B)	PR
273285	WELL	PR	11/01/2005	GW	045-10231	HMU 3-8C (I3B)	PR
273286	WELL	AL	10/12/2006	LO	045-10233	GMU 35-13D (I3B)	AL
273287	WELL	PR	10/12/2005	GW	045-10232	HMU 2-12B (I3B)	PR

General Comment:

Shared tank battery on location ID 334940

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

9

Comment:

Corrective Action:

Date:

Type: Vertical Heated Separator

9

Comment:

Corrective Action:

Date:

Type: Flow Line

#

Comment: [NTO, Comply with Rule 603.f . see photos](#)Corrective Action: [24 hrs to lock out tag out. 30 days to remove riser](#)

Date:

Type: Gas Meter Run

1

Comment:

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities									
Facility ID:	267971	Type:	WELL	API Number:	045-09227	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	267979	Type:	WELL	API Number:	045-09234	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	267980	Type:	WELL	API Number:	045-09235	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	267983	Type:	WELL	API Number:	045-09237	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	273281	Type:	WELL	API Number:	045-10228	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	273282	Type:	WELL	API Number:	045-10230	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	273284	Type:	WELL	API Number:	045-10234	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	273285	Type:	WELL	API Number:	045-10231	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:						Date:			

Facility ID:	273286	Type:	WELL	API Number:	045-10233	Status:	AL	Insp. Status:	AL
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Facility ID:	273287	Type:	WELL	API Number:	045-10232	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing WellComment: [Plunger lift](#)

Corrective Action:

Date:

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Berms	Pass					
		Culverts	Pass			
		Ditches	Pass			
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666803475	NT0 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4220630
666803476	NT0 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4220631