

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/09/2017

Submitted Date:

08/09/2017

Document Number:

689500078

FIELD INSPECTION FORM

Loc ID 314265 Inspector Name: GRANAHAN, KYLE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 16700
Name of Operator: CHEVRON USA INC
Address: 6301 DEAUVILLE BLVD
City: MIDLAND State: TX Zip: 79706

Findings:

5 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|--------------|------------------|---------|
| Peterson, Diane | 970-675-3842 | dlpe@chevron.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 228144 | WELL | PR | 02/15/2007 | OW | 103-01062 | LEVISON 6 | PR |

General Comment:

[Well flows to remote tank battery - facility id # 426403](#)

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|---------------------------|-------|--|
| | Type WELLHEAD | | |
| | Comment: Present/complete | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|--------------|-------|--|
| Comment: | 970-675-3700 | | |
| Corrective Action: | | Date: | |

Overall Good:

Spills:

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|
| | | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

| | | | | |
|--------------------------|-----|-------|--|-----------------|
| | | | | corrective date |
| Type: Deadman # & Marked | # 4 | | | |
| Comment: | | | | |
| Corrective Action: | | Date: | | |
| Type: Submersible Pump | # 1 | | | |
| Comment: | | | | |
| Corrective Action: | | Date: | | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 228144 Type: WELL API Number: 103-01062 Status: PR Insp. Status: PR

Producing Well

Comment: PR - via submersible pump unit, no leaks/venting - cellar with grated cover present.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms | Pass | | | | | |
| Compaction | Pass | | | | | |
| Gravel | Pass | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT