



photo 1: Facing southeast toward the former tank battery site. There is tall undesirable weeds (Kochia) throughout the site.



photo 2: Facing southwest toward of the former tank battery site. There is gravel that remains, soils are compacted, and there is undesirable/noxious weeds throughout the site.



photo 3: Facing southeast toward the location.



photo 4: The electric utilities remain at the location and the location has not been reclaimed per rule 1004.