



photo 1: Facing northeast toward the former tank battery area.



photo 2: There is a pipe riser that remains at the former battery site Lat/Long:39.84499,-104.45152. It appears to have been disassembled since previous inspection however, riser still remains.



photo 3: The riser is locked and tagged out.



photo 4: Facing east toward the well site. The wheat crop has recently been harvested.