



photo 1: Facing north toward the former tank battery area.



photo 2: There is a metal rod and plastic pvc pipe that remains at the tank battery site.



photo 3: The arrow points to an area of subsidence beginning to occur.



photo 4: There is an abandoned riser that remains at Lat/Long:39.84450,-104.45200.



photo 5: Facing west toward the well site. There is tall undesirable weed debris at the site.



photo 6: Facing southwest toward the surrounding crop field.