

Inspection Photos

8/9/2017

Operator: GREMLIN OIL CO - 35850

Location ID: 395142

Inspection Doc. Number: 675103810

Morgan County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: GREMLIN OIL CO - 35850
Location ID: 395142



Photo 1: Photo taken from the location, facing north. Photo shows vegetation over the reclamation area.



Photo 2: Photo taken from the location, facing east. Photo shows vegetation over the reclamation area.

Inspection Photos
Operator: GREMLIN OIL CO - 35850
Location ID: 395142



Photo 3: Photo taken from the location, facing south. Photo shows vegetation over the reclamation area.



Photo 4: Photo taken from the location, facing wes. Photo shows vegetation over the reclamation area.