



photo 1: Facing south toward the access road standing from the county road.



photo 2: Facing south toward the location. A portable facility remains at the location which has fallen over.



photo 3: Facing southwest at the location. This area has not been reclaimed.



photo 4: There is gravel spread at the location and soil piles remain.