

Inspection Photos
Location Name: A.P. Urie 2
API: 05-081-05288



Photo 1. Overview of location taken at entrance facing northwest.

Inspection Photos
Location Name: A.P. Urie 2
API: 05-081-05288



Photo 2. 2 – 2” steel risers at 40.38563, -108.13577



Photo 3. Stained soil at wellhead. Containers without secondary containment on right side of picture. 1 – 2” steel riser.