



Photo 1: View of the project area from the northwestern corner facing center.



Photo 2: View of the western portion of the project area from the northwestern corner of the well pad facing southward. Revegetation is progressing with grasses such as squirreltail (*Elymus elymoides*) and purple threeawn (*Aristida purpurea*).



Photo 3: View of the northern portion of the project area from the northwestern corner of the well pad facing eastward.



Photo 4: View of the southern portion of the project area from the southwestern corner facing eastward.



Photo 5: View of plastic debris in the southern portion of the project area.



Photo 6: View of open cellar filled with water at the well head.