

Inspection Photos

Location Name: Wagner 11-65 11-1H

API: 05-123-33110



Battery sign east side of production tanks



Production tanks looking north



Inspection Photos

Location Name: Wagner 11-65 11-1H

API: 05-123-33110



Production tanks looking south, recirc pump



Stained soil inside of heater treater at oil and water inlets on south side



Inspection Photos

Location Name: Wagner 11-65 11-1H

API: 05-123-33110



Stained soil inside of heater treater at oil and water inlets on the north side



Sediment movement on cut slope at north end of location



Inspection Photos

Location Name: Wagner 11-65 11-1H

API: 05-123-33110



Battery looking south from heater treater



Weeds need controlled, east side of production tanks



Inspection Photos

Location Name: Wagner 11-65 11-1H

API: 05-123-33110



Weeds need controlled, east side of pump jack



Trash on east side of pump jack



Inspection Photos

Location Name: Wagner 11-65 11-1H

API: 05-123-33110



Wellhead sign with inaccurate operator information and inaccurate emergency contact information



Stained soil northwest side of pump jack. Trash needs picked up

Inspection Photos

Location Name: Wagner 11-65 11-1H

API: 05-123-33110



Stained soil south side of wellhead looking north. Draining off of pump jack skid as well



Erosion at entrance of location, west side



Inspection Photos

Location Name: Wagner 11-65 11-1H

API: 05-123-33110



Erosion at entrance of location, west side



Actively growing weeds at location entrance, west side



Inspection Photos

Location Name: Wagner 11-65 11-1H

API: 05-123-33110



Actively growing weeds at location entrance, east side



Unused equipment northwest side of pump jack



Inspection Photos

Location Name: Wagner 11-65 11-1H

API: 05-123-33110



Unused 3" load line next to production water tank

