

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/28/2017

Submitted Date:

08/04/2017

Document Number:

679100104

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: KUBECZKO, DAVE On-Site Inspection 2A Doc Num: 401252504

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96735
Name of Operator: WILLIFORD RESOURCES, L.L.C.
Address: 6506 S LEWIS AVE STE 102
City: TULSA State: OK Zip: 74136

Findings:

- 1 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Dave Kubeczko		dave.kubeczko@state.co.us	
Linda Callahan		lcallahan@swbell.net	

General Comment:

Date of Inspection: 06-28-17
Type of Inspection: Form 2A Pre-Permit Approval Onsite
Location Name: West Combustor Facility
Form 2A # 401252504
Location ID #: NA
API #: NA
Conducted onsite for proposed combustor pad location (approximately 30' by 30') with operator on 06-28-17; location will have a gravel pad, combustor, liquids knock-out tank, and flowlines; location is near existing gathering line so minimal disturbance for hookup will be needed; location is dry pasture and will not require interim reclamation since the combustor will operate for the lifetime of the oil and gas wells in this field; location should be inspected once constructed, flowline tested, and in operation.

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401366530	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4217973