

A photograph showing a multi-lane asphalt road with a white shoulder line on the right. A wide, light-colored band of sediment or dirt is tracked across the road surface, originating from a construction site on the left. The construction site features a long, tan-colored retaining wall, a red truck, and several white vehicles. Trees and a house are visible in the background under a cloudy sky.

sediment tracked onto I-25 frontage road from location 445345

8.8.2017 08:53