

Photo#1:
Overview of Location to West.



July 31, 2017

Photo#2:
Interim Reclamation area with failed seeding

Photo#3:
Close up of Kochia, the main emergent species



July 31, 2017

Photo#4:

Interim Reclamation area where desirable species have emerged..



July 31, 2017

Photo#5:
Views of Well head and Cellar



Photo#6:



July 31, 2017