



photo 1: Facing northwest toward the former tank battery site.



photo 2: The pipe riser identified in the previous inspection appears to be a vent pipe for pipeline.



photo 3: There are 3 pipes sticking out of the ground at the former tank battery site along Wolf Creek Rd.



photo 4: The electric utility to the location appears to have been removed however, the main powerline remains.