

Inspection Photos
Location Name: Elk Springs Unit 14-8
API: 05-081-06765



Photo 1. Risers on location.



**Photo 2. Landfarm material with unconsolidated berm.
(1 of 3)**

Inspection Photos
Location Name: Elk Springs Unit 14-8
API: 05-081-06765



**Photo 3. Landfarm material with unconsolidated berm.
(2 of 3)**



**Photo 4. Landfarm material with unconsolidated berm.
(3 of 3)**