

Inspection Photos  
Location Name: Federal 1  
API: 05-081-06352



**Photo 1. 3 – 2" steel risers on location.**



**Photo 2. 2" riser at wellhead.**

Inspection Photos  
Location Name: Federal 1  
API: 05-081-06352



**Photo 3. Overgrown access road. Photo taken at location edge facing northeast.**



**Photo 4. Overgrown access road. Photo taken halfway between main road and location.**