

GR 24-32 Pad
Api: 05-045-06835
Inspection # 689700145



Location photo

GR 24-32 Pad
Api: 05-045-06835
Inspection # 689700145



Erosion of access road at entrance of location

GR 24-32 Pad
Api: 05-045-06835
Inspection # 689700145



Erosion of access road and sediment build up in ditch.