

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/15/2017

Submitted Date:

08/15/2017

Document Number:

678300877**FIELD INSPECTION FORM**Loc ID 318028 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
450833	SPILL OR RELEASE	AC			-	SPILL/RELEASE POINT	EI
451587	TANK BATTERY	AC	07/31/2017		-	Sekich 19-1L & 19-2L battery	EI

General Comment:[followup inspection](#)
[in use equipment as before \(678300794\)](#)

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

UNUSED EQUIPMENT

Comment:

unused equipment removed from location

Corrective Action:

Date:

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

spill 450833 corrected location submitted with form 27 also

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities								
Facility ID:	450833	Type:	SPILL OR	API Number: -	Status:	AC	Insp. Status:	EI
Facility ID:	451587	Type:	TANK	API Number: -	Status:	AC	Insp. Status:	EI